IMPORTANT SAFETY INFORMATION

Date:	09/28/15
To:	C30HDG-C30HDGWR Series Concrete Pump Owners
From:	Multiquip Product Department
Subject:	Fuse Box Mounting Orientation Modification — MANDATORY UPDATE



Dear Multiquip Customer,

Our records indicate that your company purchased one or more C30HDG-C30HDGWR Series Concrete Pumps. Multiquip is alerting the owners of C30HDG-C30HDGWR concrete pumps of updates required to the pump. Some C30HDG and C30HDGWR units may have been shipped with the fuse box incorrectly installed upside down which allows water to be trapped inside the cover causing an electrical system shortage.

The accompanying bulletin lists the problems and explains the actions required to correct these problems.

Failure to perform this inspection may result in:

Electrical system shortage.

If this concrete pump has been resold, please forward this bulletin to the new owner.

Labor Allowance: 10 minutes total flat rate for all modifications.



Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari gani yaputanani. Na sali Ina Katalari mu Pani si Akazarata ke tarata da da Kata Alak Ying Katalari katalari Manan di Katan Rajata (Alaman) Katalari katalari padi Katana Raja (Katalari	SCOL Brand	
When Source Mades The DifferenceIII Sectors	* Vold	Alberts
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
a Print Street S	Bit: Brailforte	Api pra con ·
State Second and Areas	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description from Yes Are Locking For	CdPlac
		De
	21/14	Evel *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar

Service Bulletin

C30HDG-C30HDGWR Concrete Pump Fuse Box Orientation Modification

Product Group:	Date Issued:	Service Bulletin No.
Concrete Pump	09/28/15	PCH20150924
Bulletin Type		Models/Series Affected: C30HDG CONCRETE PUMP
X Mandatory		I 140702, 140704, 141102, 150103, 40903, 141104, 141103, 140502
Information Only		C30HDGWR CONCRETE PUMP
Recommended Change		S/N 141101, 150102, 140802, 150104, 140801, 140901, 14092

Details

/ULTIQUIP

Problem:

Some C30HDG and C30HDGWR units may have been shipped with the fuse box incorrectly installed upside down which allows water to be trapped inside the cover causing an electrical system shortage.

Solution:

Remove the two 10mm nuts, lock washers, and flat washers and reverse/flip over the fuse box to the correct position.

- 1. Place the concrete pump in a clean work area, free of dirt and debris with secure level ground where it will not slip or slide.
- 2. Release the latches (Figure 2) on the engine housing and pull the housing back.



Figure 2. Engine Housing Lifting

- 3. Disconnect the negative cable (**BLACK**) from the negative terminal on the battery.
- 4. Locate the fuse box in the middle of the unit (Figure 3) and check its mounting orientation. Incorrect fuse box mounting (Figure 4) will have the fuse diagram facing towards the ground.




Figure 3. Incorrect Fuse Box Mounting

5. If incorrectly mounted, use a 10mm socket to remove the two 10mm nuts, lock washers, and flat washers as shown in Figure 4.




Figure 4. Fuse Box Mounting Hardware Removal

6. Orientate the fuse box (Figure 5) with the fuse diagram facing upwards. Secure the fuse box using the two 10mm nuts, lock washers, and flat washers.




Figure 5. Correct Fuse Box Mounting

- 7. Reconnect the negative cable (**BLACK**) to the negative terminal on the battery.
- 8. Close the engine housing and secure with the latches.

Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari gani yaputanani. Na sali Ina Katalari mu Pani si Akazarata ke tarata da da Kata Alak Ying Katalari katalari Manan di Katan Rajata (Alaman) Katalari katalari padi Katana Raja (Katalari	SCOL Brand	
When Source Mades The DifferenceIII Sectors	* Vold	A(8.5.5
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
a Print Street S	Bit: Brailforte	Api pra con ·
State Second and Areas	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description from Yes Are Locking For	CdPlac
		De
	21/14	Evel *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar