

Service Bulletin No. LT20060512 Subject: Muffler Tail Pipe, Engine. Sensor Harness Clamp and Tie-Down Negative Battery Cable Model: LT-12D, LT12D50SA, LT12D50GB Product Group: Light Tower/Generator

SERVICE BULLETIN

Mandatory

Information

Group: LT

Recommended Change

Series/Parts Affected:

Machines Affected:

ModelSerial number Range

LT-12D.....S/N 900854-903580 LT-12D50SA....S/N 902343-903284 LT-12D50GB....S/N 902409-902426

SERVICE INFORMATION

INFORMATION UPDATE: The above referenced serial number light towers may experience the following:

Problem 1:

• The inside diameter of the engine sensor wire harness clamp is slightly oversized allowing the engine sensor wire harness to slide down enough to rub through the wire insulation causing an electrical short to ground that can destroy the control panel

Solution 1:

• Slide the wire harness up through the clamp and squeeze the clamp to hold the harness in its new position, preventing any contact between the wires exiting the harness and the clamp.

Problem 2:

• Muffler fractures or breakage have occurred in and around the muffler inlet pipe. These fractures are due to the weight and length of the current tail pipe.

Solution 2:

• Replace existing muffler tail pipe and muffler mounting bracket. New muffler tail pipe is lighter and shorter. Install muffler support kit P/N 29939.

Problem 3:

• Negative battery cable is not secured. Possibility exists of negative battery cable making contact with <u>HOT!</u> muffler surface.

Solution 3:

Using a tie-wrap, secure the negative (**BLACK**) battery cable to the cable clamp securing the positive (**RED**) battery cable.

05/12/2006



Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari ganity apulartari. Na sali Ina Badu mu Parla na Asaratari ke tarata da da Katani Alak Ying Katala da	SCOL Brand	
When Source Mades The DifferenceIII Sections	* Vold	A(8.5.5
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
An Andrew Territory Territory Territory Territory Territory Territory	Bit: Brailforte	Api pra con ·
State Second and Area	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description from Yes Are Locking For	CdPlac
		De
	21/14	Evel *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar

PARTS INFORMATION				
Quantity	Part #	Description	Remarks	
1	29939	Kit, Muffler Support, LT12D		

INSTALLATION INSTRUCTIONS

WORK SAFELY!

order your Only a *qualified service technician* with proper training should perform this installation.

Required Tools/Materials

- 3/8" Ratchet with extension (6-inches)
- 1/2" Socket Standard
- ¹/₂ Socket Deep •
- 6 mm Allen Wrench
- 3/4" Combination Wrench
- Flat Head Screwdriver •
- Pliers

Table 1. Muffler Support Kit Parts List				
Part Number	Description	Quantity		
0161 C	Washer, Lock 5/16" MED.	2		
1928	Screw, HHC M8 1.25 X 40 MM	2		
29937	Bracket, Lower Muffler	1		
29938	Spacer, Muffler Bracket 38 x .75 x 63L	2		
29645	Tail Pipe (exhaust), Deutz/Lomb.	1		
10855	Clamp, 1-1/2" Muffler Guillotine	1		

Please make sure all muffler retrofit kit parts are accounted for. See Table 1.

Safety Procedures

Perform the following before attempting installation of the Muffler Support Kit:

- 1. Place the machine on level secure ground that is free of dirt and debris.
- Wear safety glasses; steel toed boots and any other safety protection that might be required for the modification.
- 3. Disconnect the negative battery cable from the battery.
- 4. Remove the ignition key from the ignition switch.
- 5. Allow the engine to cool before attempting to work on the muffler exhaust.

Air Cleaner Cover Removal

1. Remove the engine air filter cover and element Figures 1 and 2 to gain access to the wire harness and clamp location.



Figure 1. Air Cleaner Cover Removal



Figure 2. Air Filter Element (Removed)

Engine Wiring Harness Clamp

- 1. The crimping of the engine wiring harness clamp can be performed without having to remove the clamp.
- 2. Open the cabinet door opposite the fuel tank side and locate the engine sensor wiring harness located just below the air cleaner. Secure cabinet door by making sure latch is engaged.



Figure 3. Engine Sensor Wiring Harness

3. Slide the wiring harness upward through the clamp about 1.5 inches (30.48 mm)



Figure 4. Harness Properly Positioned

4. Once the clamp has been properly positioned (Figure 4), using a pair of pliers (Figure 5), squeeze the clamp to secure the harness in its new position.



Figure 5. Squeezing the Clamp

- 5. If the wiring inside the clamp is no longer moving up and down then it can be assumed that the engine wiring inside the clamp is secure (no movement of wires) and the crimping procedure is complete.
- 6. Reinstall air filter element and cover.

NOTE: Before removing the existing muffler tail pipe, visually inspect area in around muffler the muffler inlet pipe to determine if fractures or breakage is visible. If fractures or breakage is visible replace existing muffler tail pipe section. If no fractures are visible (no breakage) proceed to the "Negative Battery Cable Tie-Down Installation Procedure".

Tail Pipe Removal

This procedure will involve the removal of the existing muffler tail pipe.

- 1. Open the cabinet door on the fuel tank side. Secure cabinet door by making sure latch is engaged.
- Using a 3/8" ratchet with a ½" deep socket remove the 2 flange nuts that secure the muffler clamp (Figure 2) to the tail pipe.
- 3. After clamp has been removed, discard clamp and associated hardware. Clamp and mounting hardware will not be used again.



Figure 6. Muffler Clamp Removal

- 4. Move the muffler tailpipe from side to side while pulling down on the tail pipe. Repeat this procedure a few times to dislodge the tail pipe from the muffler.
- 5. If the tailpipe is having difficulty being removed from the muffler, strike the tail pipe a few times with a rubber mallet to help dislodge the tail pipe from the muffler.
- 6. Discard tailpipe and clamp. Tailpipe and clamp will not be used again.
- 7. Close cabinet door.

Muffler Bracket Removal

This procedure will involve the removal of the existing muffler bracket.

- Using a 3/8" ratchet with a ½" socket remove the bolt (Figure 3) that secures the muffler bracket to the engine.
- 2. Remove muffler-mounting bracket and discard, it will not be used again. Retain all mounting hardware (bolts, flat washers and lock washers). Some of this hardware will be used later.



Figure 7. Muffler Bracket Removal

Tail Pipe Installation

This procedure will involve the installation of the new muffler tailpipe and clamp.

- 1. Remove the new tail pipe (P/N 29645) and clamp (P/N 10855) from the muffler support kit.
- 2. Insert the tailpipe section into the muffler. Place the muffler clamp between the tailpipe and the muffler.
- Using a 3/8" ratchet with a ½" deep socket, install the U-bolt, clamp and retaining flange nuts (2) that secure the muffler clamp (Figure 2) to the tail pipe.
- 4. Position the tail pipe (Figure 4) so that the exhaust is facing the rear bumper of the light tower/generator. Tighten clamp securely.

New Muffler Bracket Installation

This procedure will involve the installation of the new muffler bracket.

- 1. Remove the new muffler mounting bracket (P/N 29937), two lock washers (P/N 0161 C), two spacers (P/N 29938) and two hex head cap screws (P/N 29938) from the muffler support kit.
- Using the hex head cap screw (2) install the new muffler bracket between the engine and the muffler (Figure 5). Remember to place spacer (2) between engine and bracket. Only hand-tighten the screws at this time. Tighten all mounting hardware securely.



Figure 8. Tail Pipe Installation



Figure 9. New Mounting Bracket

3. Using the bolt, flat washer and lock washer that secured the old muffler, insert this hardware into the <u>center hole</u> on the bracket to secure the muffler to the bracket.

 If alignment of the muffler bracket is difficult, <u>it may be</u> <u>necessary</u> to loosen the two muffler flange bolts (Figure 6) that secure the muffler to the engine.

 In addition <u>it may be necessary</u> to loosen the engine-wiring clamp (Figure 7) located just above the mounting hole for the bracket. Use a 6 mm allen wrench to loosen the clamp screw.



Figure 10. Muffler Flange



Figure 11. Engine Clamp

6. If the mounting hardware securing the muffler flange and clamp to the engine was loosened (steps 4 and 5), please re-tighten.

Negative Battery Cable Tie-Down Installation

This procedure will involve the tie-down of the negative battery cable.

1. Using a tie-wrap, secure the negative (**BLACK**) battery cable (Figure 8) to the cable clamp securing the positive (**RED**) battery cable.



Figure 12. Cable Tie (Negative Battery)

2. Close all cabinet doors, and reconnect the negative battery cable to the battery.

Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari ganity apulartari. Na sali Ina Badu mu Parla na Asaratari ke tarata da da Katani Alak Ying Katala da	SCOL Brand	
When Source Mades The DifferenceIII Sections	* Vold	Alberts
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
An Andrew Territory Territory Territory Territory Territory Territory	Bit: Brailforte	Api pra con ·
State Second and Area	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description from Yes Are Locking For	CdPlac
		De
	21/14	Evel *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar