

Service Bulletin No. TR20051026 Subject: RETROFIT SUCTION HOSE Model: STX - HTX Product Group: RIDE-ON TROWELS Date: 10/26/2005

# SERVICE BULLETIN

Group: TR

**X** Mandatory

Information

**Recommended Change** 

## Series/Parts Affected:

SUCTION HOSES

### Machines Affected

STX – S/N BF2001224 and below HTX – S/N BF2001228 and below

## SERVICE INFORMATION

It is possible that air can be induced into the hydraulic system of the trowel via the suction hoses that have the 'Worm Type Clamps" attached to them. To correct this problem, a hydraulic hose retrofit kit has been created that will replace the original "BARB" style fittings with screw-on (threaded) fittings.

## PARTS INFORMATION


Quantity	Part #	Description	Remarks
		HTX	
1		<b>KIT HTX SUCTION HOSE,</b>	
	KIT 21834	INCLUDES ITEMS LISTED	REPLACEMENTS FOR ORIGINAL
		BELOW:	
1	21814	FITTING, SUCTION	
1	21815	FITTING, PORT BLOCK	
1	21818	HOSE SUCTION	
1	21819	HOSE PORT BLOCK	
		OTV	

		STX	
1		KIT STX SUCTION HOSE,	
	KIT 21835	INCLUDES ITEMS LISTED	REPLACEMENTS FOR ORIGINAL
٠. (	5	BELOW:	
1	21814	FITTING, SUCTION	
1	21815	FITTING, PORT BLOCK	
	21816	HOSE SUCTION	
XY	21817	HOSE PORT BLOCK	

#### INSTALLATION INSTRUCTIONS

- 1. For removal and installation of hydraulic hoses, reference Figure 1.
- 2. For ease and accessibility, it may be convenient to place the trowel on jack-stands. Make sure the work area is clean and free of debris.
- 3. Follow all safety guidelines, to prevent injury to personnel or damage to the equipment.
- 4. Standing at the rear of the trowel, *remove the right panel*. This will help gain access to the hydraulic hoses and fittings.
- 5. Remove the bottom *suction hose* from the hydraulic suction filter as shown in Figure 1, step 1.
- Remove the other end of the *suction hose* from the side of the T-fitting (Figure 1, step 2). It may become necessary to remove other hoses to gain complete access to the hose connection point. If so, take care in removing the other hoses.
- 7. Next, remove the *port block hose* from the top of the T-fitting (Figure 1, step 3).
- 8. Remove the other end of the *port block hose* from the port block fitting (Figure 1, step 4).
- Install new screw-on fitting (threaded P/N 21814) into hydraulic filter (Figure 1, step 5). Connect mating end of *new suction hose* (HTX - P/N 21818 or STX - P/N 21816) to this fitting (Figure 1, step 5).
- 10. Connect the other end of *new suction hose* to side of T-fitting (Figure 1, step 6).
- 11. Connect one end of *new port block hose* (H TX P/N 21819 or STX P/N 21817) to top of T-fitting (Figure 1, step 7).
- Install new screw-on fitting (threaded P/N 21815) into port block (Figure 1, step 8). Connect mating end of *new port block hose* (HTX - P/N 21819 or STX - P/N 21817) to this fitting (Figure 1, step 8).
- 13. Make sure all hose connections are tight. If any other hoses were removed, reconnect them.
- 14. Reinstall back panel.
- 15. Start trowel and check for leaks on all hoses that were changed or removed.
- 16. Check the hydraulic fluid level and fill as needed.
- 17. Test all functions of the trowel and make sure trowel is working correctly.

,0 to Dif



Search Website by Part Number <b>Discount</b>	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari gani yaputanani. Na sali Ina Katalari mu Pani si Akazarata ke tarata da da Kata Alak Ying Katalari katalari Manan di Katan Rajata (Alaman) Katalari katalari padi Katana Raja (Katalari	SCOL Brand	
When Source Mades The DifferenceIII Sectors	* Vold	A(8.5.5
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
a Print Street S	Bit: Brailforte	Api pra con ·
State Second and Area	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description fam You Are Locking For	CdPlac
		<b>N</b> 2
	21/14	Ermi *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

### Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar