

REVISED STARTING SERIAL # 120410049

### **PARTS LIST MANUAL**

### **MODEL SB14**







ELECTRIC MODEL WITH VACUUM TUBE



AIR POWERED MODEL

## 14" UPCUT - CONCRETE AND ASPAHLT WALK BEHIND SAWS

| SKU#      | MODEL#        | POWER OPTION                             |
|-----------|---------------|--|
| 43100     | SB14-9H       | HONDA GASOLINE ENGINE MODEL GX270U1-QXC9 |
| 42500     | SB14-11H      | HONDA GASOLINE ENGINE MODEL GX340U1-QXC9 |
| 48200     | SB14-13H      | HONDA GASOLINE ENGINE MODEL GX390U1-QXC9 |
| 42600     | SB14-5B/230/1 | BALDOR ELECTRIC MOTOR 5HP 1PH 60Hz 230V  |
| 40650-230 | SB14-5B/230/3 | BALDOR ELECTRIC MOTOR 5HP 3PH 60Hz 230V  |
| 40650-460 | SB14-5B/460/3 | BALDOR ELECTRIC MOTOR 5HP 3PH 60Hz 460V  |
| 47200     | ASB14-5G      | GAST AIR MOTOR 5HP                       |



# PARTS FINDERS Search Website Can't Find







Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

### Need parts?

Click on this link: <a href="http://www.discount-equipment.com/category/5443-parts/">http://www.discount-equipment.com/category/5443-parts/</a> and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto, Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S. Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar



### READ AND UNDERSTAND THE OPERATORS INSTRUCTION MANUAL THOROUGHLY BEFORE ATTEMPTING TO OPERATE THIS EQUIPMENT.

Death or serious injury could occur if this machine is used improperly.



### **SAFETY MESSAGES**

Safety Instructions are proceeded by a graphic alert symbol of DANGER, WARNING, or CAUTION.



Indicates an imminent hazard which, if not avoided, will result in death or serious injury.



Indicates an imminent hazard which, if not avoided, can result in death or serious injury.



Indicates hazards which, if not avoided, could result in serious injury and or damage to the equipment.

### GASOLINE/PROPANE POWERED EQUIPMENT



- Engine exhaust from this product contains chemicals known to the State of California to cause cancer, birth defects or other reproductive harm.
- Gasoline is extremely flammable and poisonous. It should only be dispensed in well ventilated areas, and with a cool engine.
- Small gasoline engines produce high concentrations of carbon monoxide (CO) example: a 5 HP 4 cycle engine operation in an enclosed 100,000 cu. ft. area with only one change of air per hour is capable of providing deadly concentrations of CO in less than fifteen minutes. Five changes of air in the same area will produce noxious fumes in less than 30 minutes. Gasoline or propane powered equipment should not be used in enclosed or partially enclosed areas. Symptoms of CO poisoning include, headache, nausea, weakness, dizziness, visual problems and loss of consciousness. If symptoms occur - get into fresh air and seek medical attention immediately.

### **ELECTRICAL POWERED EQUIPMENT**



Extreme care must be taken when operating electric models with water present: Ensure power cord is properly grounded, is attached to a Ground-Fault-Interrupter (GFI) outlet, and is undamaged.

- Check all electrical cables be sure connections are tight and cable is continuous and in good condition. Be sure cable is correctly rated for both the operating current and voltage of this equipment.
- Improper connection of the equipment-grounding conductor can result in a risk of electric shock. Check with qualified electrician or service person if there is any doubt as to whether the outlet is properly grounded. Adhere to all local codes and ordinances.
- NOTE: In the event of a malfunction or breakdown, grounding provides a path of least resistance for the electric current to dissipate. The motor is equipped with a grounded plug and must be connected to an outlet that is properly installed and properly grounded. DO NOT modify the plug provided on the motor. If the plug does not fit the outlet have a qualified electrician install the proper receptacle.
- · Switch motor OFF before disconnecting power.

- · Do not disconnect power by pulling cord. To disconnect, grasp the plug, not the cord.
- Unplug power cord at the machine when not in use and before servicina.

### **GENERAL INSTRUCTIONS**

- Equipment should only be operated by trained personnel in good physical condition and mental health (not fatigued). The operator and maintenance personnel must be physically able to handle the bulk weight and power of this equipment.
- This is a one person tool. Maintain a safe operating distance to other personnel. It is the operators' responsibility to keep other people (workers, pedestrians, bystanders, etc.) away during operation. Block off the work area in all directions with roping, safety netting, etc. for a safe distance. Failure to do so may result in others being injured by flying debris or exposing them to harmful dust and noise.
- This equipment is intended for commercial use only.
- For the operator's safety and the safety of others, always keep all guards in place during operation.
- Never let equipment run unattended.















 Personal Protection Equipment and proper safety attire must be worn when operating this machinery. The operator must wear approved safety equipment appropriate for the job such as hard hat and safety shoes when conditions require. Hearing protection MUST be used (operational noise levels of this equipment may exceed 85db). Eye protection MUST be worn at all times.



Keep body parts and loose clothing away from moving parts. Failure to do so could result in dismemberment or death.

- Do not modify the machine.
- Stop motor/engine when adjusting or servicing this equipment. Maintain a safe operating distance from flammable



materials. Sparks from the cutting-action of this machine can ignite flammable materials or vapors.

### **DUST WARNING**



Some dust created by power sanding, sawing, grinding, drilling, and other construction activities contains chemicals known to cause cancer, birth defects, or other reproductive harm. Some examples of these chemicals are:

- Lead from lead-based paints, and
- Crystalline silica from bricks and concrete and other masonry products.

Your risk of exposure to these chemicals varies depending on how often you do this type of work. To reduce your risk: work in a well ventilated area, use a dust control system, such as an industrial-style vacuum, and wear approved personal safety equipment, such as a dust/particle respirator designed to filter out microscopic particles.




# PARTS LIST MANUAL MODEL SB14

### **TABLE OF CONTENTS**

| Section   | Page Number    |
|---|----------------|
| Safety Messages and General Instructions                            | 2              |
| How To Order Replacement Parts                                      | 3              |
| Illustration 1: Main Grouping                                       |                |
| Illustration 2: Arbor & Blade Guard Grouping                        | 6, 7           |
| Illustration 3: Blade Guard Assembly with 2" Vacuum Port (Optional) | 8, 9           |
| Illustration 4: Water Tank Assembly (Optional)                      | 10, 11         |
| Illustration 5: Engine Grouping                                     |                |
| Illustration 6: Single Phase Motor Grouping                         | 14, 15         |
| Illustration 7: Three Phase Motor Grouping                          | 16, 17         |
| Illustration 8: Air Motor Grouping                                  | 18, 19         |
| Wiring Diagram for Rotary Switch                                    | 20             |
| Wiring Diagram for Starter  | 21             |
| Wiring Diagram for 1 Phase 60Hz Motor - Baldor L3608TM              | 22             |
| Wiring Diagram for 3 Phase 60Hz Motor - Baldor M3613T               | 23             |
| Wiring Diagram for Honda Engine                                     | 24             |
| Notes   | 25             |
| Decals  | 26, 27         |
| Limited Equipment Warranty  | 28 (Back Page) |




### **ILLUSTRATION 1: MAIN GROUPING**



|      | PARTS LISTING - ILLUSTRATION 1: MAIN GROUPING |                              |      |          |        |                                       |  |
|------|---|------------------------------|------|----------|--------|---------------------------------------|--|
| ITEM | PART#   | DESCRIPTION                  | QTY. | ITEM     | PART # | DESCRIPTION                           | QTY.   |
| 1    | 80002   | MAIN FRAME, SB-14            | 1    | 24       | 10009  | WASHER, FLAT 3/4 SAE ZINC             | 2  |
| 2    | 81009   | GUIDE BAR, SB-14             | 1    | 25       | 81003  | GUIDE FIN, REAR, SB-14                | 1  |
| 3    | 10309   | SCREW, CAP 3/8-24 X 1-1/4    | 1    | 26       | 10429  | NUT, HEX JAM 3/4-16 ZINC              | 4  |
| 4    | 10025   | WASHER, FLAT 3/8 SAE ZINC    | 2    | 27       | 10609  | WASHER, LOCK,                         | 2  |
| 5    | 10004   | NUT, HEX LOCK 3/8-24 ZINC    | 1    |          |        | INT. TOOTH 3/4"                       |  |
| 6    | 80037   | RETAINER, BLADE GUARD        | 1    | 28       | 81024  | HANDLE BAR, SB-14                     | 1  |
| 7    | 10018   | SCREW, CAP 1/4-20 X 3/4      | 1    | 29       | 10029  | SCREW, CAP 3/8-24 X 1-3/4             | 2  |
| 8    | 10602   | WASHER, FLAT 1/4 SAE ZINC    | 1    | 30       | 10025  | WASHER, FLAT 3/8 SAE ZINC             | 4  |
| 9    | 10015   | NUT, HEX LOCK 1/4-20 ZINC    | 1    | 31       | 10004  | NUT, HEX LOCK 3/8-24 ZINC             | 2  |
| 10   | 80018   | FORK, SB-14                  | 1    | 32       | 10608  | GRIP, HAND 1" MODEL AT                | 2  |
| 11   | 80028   | WHEEL 6 X 2 X 3/4"BRG.       | 1    | 33       | 65019  | HANDWHEEL, SMALL W/<br>5/8-8 X 13"ROD | 1  |
| 12   | 80023   | AXLE TUBE 3/4ODX1/2IDX3-7/8L | 1    | 24       | 81001  |                                       | 1  |
| 13   | 80022   | SPACER, WHEEL                | 2    | 34       | 14023  | SCREW, CAP 1/2-13 X 4                 | 1  |
|      |   | 13/16"ID X 13/16"L           | 4    | 35       | 80009  | KNOB, BALL 1-3/8 W/ 1/2-13THD,        | <del>                                     </del> |
| 14   | 65017   | SCREW, CAP 1/2-20 X 5 ZINC   | 1    | 36       |        | BEARING, BALL 5/8" 2-HOLE             | 1  |
| 15   | 10312   | WASHER, FLAT 1/2 SAE ZINC    | 2    | 37       | 10412  | BOLT, CARRIAGE 1/4-20 X 1             | 2  |
| 16   | 10205   | NUT, HEX LOCK 1/2-20 ZINC    | 1    | 38       | 10602  | WASHER, FLAT 1/4 SAE ZINC             | 2  |
| 17   | 10308   | SCREW, CAP 1/2-20 X 1-1/2    | 1    | 39       | 10861  | NUT, KEPS LOCK 1/4-20 ZINC            | 2  |
| 18   | 10312   | WASHER, FLAT 1/2 SAE ZINC    | 1    | 40       | 55010  | SPACER, HANDWHEEL<br>5/8"ID X 3/4"L   | 1  |
| 19   | 10154   | NUT, HEX NYLON LOCK 1/2-20   | 1    | 41       | 10096  | COLLAR, LOCKING 5/8"ID                | 1  |
| 20   | 10407   | NUT, HEX LOCK 1/2-13 ZINC    | 1    | $\vdash$ |        | '                                     | $\vdash$   |
| 21   | 10408   | SCREW, CAP 1/2-13 X 9        | 1    | 42       | 10808  | FITTING, GREASE 1/4-28<br>STRAIGHT    | 1  |
| 22   | 10406   | SCREW, CAP 3/4-16 X 4        | 2    | 43       | 81025  | LINKAGE, CUT CONTROL                  | 1  |
| 23   | 79013   | WHEEL, 8 X 2-1/2 X 3/4"BRG.  | 2    |          |        | 5/8-8 THD.                            |  |



### ILLUSTRATION 2: ARBOR & BLADE GUARD GROUPING






| PARTS | LISTING - ILL | USTRATION 2: ARBOR & BLADE GUARD GROU    | JPING |
|-------|---------------|--|-------|
| ITEM# | PART#         | DESCRIPTION                              | QTY.  |
| 1     | 81008A        | ARBOR ASSEMBLY, SB14 GAS/ELEC.           | 1     |
|       | 81008B        | ARBOR ASSEMBLY, ASB14 AIR POWERED        | 1     |
| 2     | 81008         | ARBOR SHAFT W/ BACKING PLATE, SB-14      | 1     |
| 3     | 80005         | ARBOR BLADE CAP 3-1/2" W/ 3/4"HOLE       | 1     |
| 4     | 10609         | WASHER, LOCK, INT. TOOTH 3/4"            | 1     |
| 5     | 10403         | NUT, HEX JAM 3/4-10 ZINC                 | 1     |
| 6     | 77009         | BEARING, BALL 3/4" 4-HOLE FLANGE         | 2     |
| 7     | 10088         | KEY 3/16SQ X 2-1/2                       | 1     |
| 8     |               | SHEAVE                                   | 1     |
|       | 81011         | 3"OD X 3GR.A X 3/4"BORE (GAS & ELEC.)    |       |
|       | 80016         | 3"OD X 2GR.B X 3/4BORE (AIR POWERED)     |       |
| 9     | 81007         | BELT AX-33 (GASOLINE & ELECTRIC POWERED) | 3     |
|       | 10251         | BELT B-34 (AIR POWERED)                  | 2     |
| 10    | 10309         | SCREW, CAP 3/8-24 X 1-1/4 ZINC           | 8     |
| 11    | 10811         | WASHER, LOCK 3/8 ZINC                    | 8     |
| 12    | 10014         | NUT, HEX 3/8-24 ZINC                     | 8     |
| 13    | 80004         | GUARD, BLADE, SB-14                      | 1     |
| 14    | 81004         | NOZZLE, COOLANT 1/8MPT W/ 4"TUBES        | 1     |
| 15    | 65017         | SCREW, CAP 1/2-20 X 5 ZINC               | 1     |
| 16    | 10312         | WASHER, FLAT 1/2 SAE ZINC                | 3     |
| 17    | 10072         | NUT, HEX 1/2-20 ZINC                     | 1     |
|       |               | NOTE: USE RED LOCTITE™                   |       |
| 18    | 10087         | BOLT, CARRIAGE 3/8-16 X 1-3/4            | 1     |
| 19    | 11741         | WASHER, NYLON 1"OD X.518ID X.08THK       | 1     |
| 20    | 10034         | BUSHING, RUBBER 1"OD X 3/8ID X 5/8T      | 1     |
| 21    | 10025         | WASHER, FLAT 3/8 SAE ZINC                | 1     |
| 22    | 80011         | KNOB, 3-PRONG W/ 3/8-16 THD.             | 1     |
| 23    | 11562         | BARB ELBOW 90, 3/8HOSE X 1/8MPT          | 1     |
| 24    | 50069         | CLAMP, HOSE, SAE #6, ADJ. TO 13/16       | 2     |
| 25    | 56317         | HOSE, WATER 3/8"ID X 48"L (GAS & AIR)    | 1     |
|       | 80039         | HOSE, WATER 3/8"ID X 33"L (ELECTRIC)     | 1     |
| 26    | 10982         | TIE, CABLE, BLACK NYLON 11-1/4"          | 1     |
| 27    | 10799         | BARB ELBOW 90, 3/8HOSE X 1/4MPT          | 1     |
| 28    | 56022         | BRACKET, WATER VALVE                     | 1     |
|       |               | (MOUNTED ON OPP. SIDE FOR ELEC. UNITS)   |       |
| 29    | 10711         | VALVE, BALL 1/2 FPT                      | 1     |
| 30    | 80021         | CONN., SWIVEL FEM. 3/4HOSE X 1/2MPT      | 1     |
| 31    | 10846         | SCREW, CAP STSHW 1/4-20 X 1/2            | 2     |
| 32    | 10038         | WASHER, LOCK 1/4 ZINC                    | 2     |



### ILLUSTRATION 3: BLADE GUARD ASSEMBLY WITH 2" VACUUM PORT






|   | PARTS LISTING - ILLUSTRATION 3:                     |                                     |      |  |  |
|---|---|-------------------------------------|------|--|--|
| BL  | BLADE GUARD ASSEMBLY WITH 2" VACUUM PORT (OPTIONAL) |                                     |      |  |  |
| ITEM#   | PART#   | DESCRIPTION                         | QTY. |  |  |
| 1-14  | 81030   | GUARD ASSY. W/ VAC PORT, SB-14      | 1    |  |  |
| 1   | 04004   | (INCLUDES ITEMS 1 THRU 14)          |      |  |  |
| 1   | 81031   | GUARD ONLY W/ VAC PORT, SB-14       | 1    |  |  |
| 2   | 81032   | GUARD VAC PORT, SLIDING, SB-14      | 1    |  |  |
| 3   | 10018   | SCREW, CAP 1/4-20 X 3/4             | 2    |  |  |
| 4   | 10013   | NUT, HEX 1/4-20 ZINC                | 2    |  |  |
| 5   | 81033   | WHEEL, BLADE GUARD VAC PORT, SB-14  | 2    |  |  |
| 6   | 10015   | NUT, HEX LOCK 1/4-20 ZINC           | 2    |  |  |
| 7   | 11658   | SCREW, CAP 1/4-20 X 2-3/4           | 1    |  |  |
| 8   | 10602   | WASHER, FLAT 1/4 SAE ZINC           | 2    |  |  |
| 9   | 10150   | NUT, HEX NYLON LOCK 1/4-20 ZINC     | 1    |  |  |
| 10*   | 81004   | NOZZLE, COOLANT 1/8MPT W/ 4"TUBES   | 1    |  |  |
| 11*   | 11562   | BARB ELBOW 90, 3/8HOSE X 1/8MPT     | 1    |  |  |
| 12  | 81034   | BRKT., BLADE GUARD CENTERING,SB14   | 1    |  |  |
| 13  | 10018   | SCREW, CAP 1/4-20 X 3/4             | 1    |  |  |
| 14  | 10015   | NUT, HEX LOCK 1/4-20 ZINC           | 1    |  |  |
| 15*   | 65017   | SCREW, CAP 1/2-20 X 5 ZINC          | 1    |  |  |
| 16*   | 10312   | WASHER, FLAT 1/2 SAE ZINC           | 3    |  |  |
| 17*   | 10205   | NUT, HEX LOCK 1/2-20 ZINC           | 1    |  |  |
| 18*   | 10087   | BOLT, CARRIAGE 3/8-16 X 1-3/4       | 1    |  |  |
| 19*   | 11741   | WASHER, NYLON 1"OD X.518ID X.08THK  | 1    |  |  |
| 20*   | 10034   | BUSHING, RUBBER 1"OD X 3/8ID X 5/8T | 1    |  |  |
| 21*   | 10025   | WASHER, FLAT 3/8 SAE ZINC           | 1    |  |  |
| 22*   | 80011   | KNOB, 3-PRONG W/ 3/8-16 THD.        | 1    |  |  |
| *NOTE: THESE ITEMS ARE THE SAME ITEMS USED WITH THE STANDARD BLADE GUARD SHOWN IN ILLUSTRATION 2. |   |                                     |      |  |  |



### **ILLUSTRATION 4: WATER TANK ASSEMBLY**





| PARTS LISTING - ILLUSTRATION 4: WATER TANK ASSEMBLY |       |                                     |      |  |
|---|-------|-------------------------------------|------|--|
|   |       | OPTIONAL - PART # 51090             |      |  |
| ITEM#   | PART# | DESCRIPTION                         | QTY. |  |
| 1   | 52031 | DRUM, PLASTIC 5 GALLON, 3/4NPT CAP  | 1    |  |
| 2   | 56311 | TRAY, WATER TANK, SB-14             | 1    |  |
| 3   | 51092 | MOUNT BRKT., WATER TANK, LEFT SIDE  | 1    |  |
| 4   | 51091 | MOUNT BRKT., WATER TANK, RIGHT SIDE | 1    |  |
| 5   | 10068 | SCREW, CAP 3/8-16 X 1-1/2           | 4    |  |
| 6   | 10025 | WASHER, FLAT 3/8 SAE ZINC           | 8    |  |
| 7   | 10811 | WASHER, LOCK 3/8 ZINC               | 4    |  |
| 8   | 10404 | NUT, HEX 3/8-16 ZINC                | 4    |  |
| 9   | 10053 | SCREW, CAP 5/16-18 X 3/4            | 4    |  |
| 10  | 10213 | WASHER, FLAT 5/16 SAE ZINC          | 8    |  |
| 11  | 10801 | WASHER, LOCK 5/16 ZINC              | 4    |  |
| 12  | 10054 | NUT, HEX 5/16-18 ZINC               | 4    |  |
| 13  | 52035 | TIE-DOWN STRAP, MOLDED RUBBER 24"   | 2    |  |
| 14  | 10905 | SCREW, CAP 1/4-20 X 1-1/4           | 2    |  |
| 15  | 10602 | WASHER, FLAT 1/4 SAE ZINC           | 2    |  |
| 16  | 10150 | NUT, HEX NYLON LOCK 1/4-20 ZINC     | 2    |  |
| 17  | 52034 | BUSHING, HEX 3/4 X 1/4 NPT NYLON    | 1    |  |
| 18  | 56312 | VALVE, BALL PVC 90°A 1/4MPT X BARB  | 1    |  |
| 19  | 50069 | CLAMP, HOSE, SAE #6, ADJ. TO 13/16  | 4    |  |
| 20  | 56315 | HOSE, WATER 3/8"ID X 24"L           | 1    |  |
| 21  | 11637 | COUPLING, QUICK-DISCONNECT 3/8"     | 1    |  |
| 22  | 56316 | HOSE, WATER 3/8"ID X 2"L            | 1    |  |



# PARTS FINDERS Search Website Can't Find







Discount-Equipment.com is your online resource for quality parts & equipment.


Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

### Need parts?

Click on this link: <a href="http://www.discount-equipment.com/category/5443-parts/">http://www.discount-equipment.com/category/5443-parts/</a> and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto, Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S. Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar


### **ILLUSTRATION 5: ENGINE GROUPING**



|       | PARTS LIST      | TING - ILLUSTRATION 5: ENGINE GROUPING   |      |
|-------|-----------------|--|------|
| ITEM# | PART#           | DESCRIPTION  | QTY. |
| 1     | 15029           | ENGINE, HONDA GX390U1-QXC9<br>WITH CYCLONE AIR CLEANER   | 1    |
| 2     | 11542           | BARB, PUSH-ON 3/8HOSE X M12-1.5MALE  | 1    |
| 3     | 56226           | HOSE, PUSH-ON 3/8"ID X 6"L   | 1    |
| 4     | 11544           | BARB, PUSH-ON 3/8 HOSE X 1/4FPT  | 1    |
| 5     | 10776           | PIPE PLUG 1/4 NPT (BRASS)  | 1    |
| 6     | 15201A<br>50084 | SWITCH W/ WIRES, ROCKER RED ON-OFF<br>ADDITIONAL PARTS REQ'D. (NOT SHOWN):<br>TERM., RING #10 16-14GA. INSULATED | 1    |
|       | 10877           | SCREW, CAP STSHW 10-24 X 1/2   | 1    |
|       | 10831           | WASHER, LOCK, INT. TOOTH #10   | 1    |
|       | 10970<br>36042  | CONN., WIRE QUICK-SPLICE 18-14 GA. CLIP, NATURAL CORD, 1/8" X 1/4"   | 1 1  |
| 7     | 3611            | CABLE, THROTTLE, LEVER-TYPE 54" (NOTE: TRIMMED TO 35")   | 1    |
| 8     | 10877           | SCREW, CAP STSHW 10-24 X 1/2   | 2    |
| 9     | 10831           | WASHER, LOCK, INT. TOOTH #10   | 2    |
| 10    | 10982           | TIE, CABLE, BLACK NYLON 11-1/4"  | 2    |
| 11    | 10071           | KEY 1/4SQ X 2-1/2  | 1    |
| 12    | 80027           | SHEAVE 3"OD X 3GR.A X 1"BORE   | 1    |
| 13    | 81007           | BELT AX-33 (1/2" x 35"OL)  | 3    |
| 14    | 81010           | MOUNT BRKT., CHANNEL, SB-14  | 2    |
| 15    | 10205           | NUT, HEX LOCK 1/2-20 ZINC (USED AS SPACER)   | 2    |
| 16    | 10087           | BOLT, CARRIAGE 3/8-16 X 1-3/4  | 2    |
| 17    | 10335           | BOLT, CARRIAGE 3/8-16 X 2-1/2 F.T.   | 2    |
| 18    | 10480           | BOLT, TAP 3/8-16 X 1-1/2 (FULL THD)  | 2    |
| 19    | 10312           | WASHER, FLAT 1/2 SAE ZINC  | 2    |
| 20    | 10025           | WASHER, FLAT 3/8 SAE ZINC  | 12   |
| 21    | 10811           | WASHER, LOCK 3/8 ZINC  | 6    |
| 22    | 10404           | NUT, HEX 3/8-16 ZINC   | 6    |




### **ILLUSTRATION 6: SINGLE PHASE MOTOR GROUPING**



| PARTS LISTING - ILLUSTRATION 6: SINGLE PHASE MOTOR GROUPING |                |   |      |  |
|---|----------------|---|------|--|
| ITEM#   | PART#          | DESCRIPTION   | QTY. |  |
| 1   | 81026          | MOTOR, BALDOR 5HP-1PH 60HZ 3450RPM<br>REPLACEMENT PARTS:              | 1    |  |
|   | 16121          | CAPACITOR, START, BALDOR EC1161C06                                    | 2    |  |
|   | 16164<br>16540 | CAPACITOR, RUN, BALDOR #OC3040F09SP<br>RESET BUTTON, BALDOR TPBRT25DB | 1    |  |
| 2   | 10740          | CONDUIT LOCK NUT 3/4 NP (INSIDE JUNCTION BOX)                         | 1    |  |
| 3   | 16539          | STRAIN RELIEF 90D X 3/4NPT .50625                                     | 1    |  |
| 4   | 81035          | WIRE HARNESS 10/3 X 30"LOA  | 1    |  |
| 5   | 81036          | WIRE HARNESS 10/3 X 40"LOA  | 1    |  |
| 6   | 40037          | PLUG, LOCKING 20A/250V L6-20P   | 1    |  |
| 7   | 40000          | CONNECTOR, LOCKING 20A/250V L6-20C                                    | 1    |  |
| 8   | 10982          | TIE, CABLE, BLACK NYLON 11-1/4"                                       | 3    |  |
| 9   | 41130          | STRAIN RELIEF 1/2NPT X .550650"                                       | 2    |  |
| 10  | 77043-1        | SWITCH ADAPTER, PG16 TO 1/2"NPT                                       | 2    |  |
| 11  | 77043          | SWITCH, ROTARY CAM ON/OFF   | 1    |  |
| 12  | 77042          | BRACKET, ROTARY CAM SWITCH  | 1    |  |
| 13  | 11663          | SCREW, MACHINE 8-32 X 1/2 RHCD ZINC (INSIDE SWITCH BOX)               | 4    |  |
| 14  | 10462          | NUT, KEPS LOCK 8-32 ZINC  | 4    |  |
| 15  | 10846          | SCREW, CAP STSHW 1/4-20 X 1/2   | 2    |  |
| 16  | 10038          | WASHER, LOCK 1/4 ZINC   | 2    |  |
| 17  | 11565          | CLAMP, LOOM, 5/8" (SAE SIZE 10)                                       | 4    |  |
| 18  | 15204          | PLUG, RECT. HOLE, PLASTIC SNAP-IN                                     | 1    |  |
| 19  |                | KEY 1/4"SQ (INCLUDED WITH MOTOR)                                      | 1    |  |
| 20  | 81006          | SHEAVE 3"OD X 3GR.A X 1-1/8"BORE                                      | 1    |  |
| 21  | 81007          | BELT AX-33 (1/2" x 35"OL)   | 3    |  |
| 22  | 81010          | MOUNT BRKT., CHANNEL, SB-14   | 2    |  |
| 23  | 10205          | NUT, HEX LOCK 1/2-20 ZINC (USED AS SPACER)                            | 2    |  |
| 24  | 10802          | BOLT, CARRIAGE 3/8-16 X 1 ZINC  | 2    |  |
| 25  | 10804          | BOLT, CARRIAGE 3/8-16 X 1-1/2 F.T.                                    | 2    |  |
| 26  | 10480          | BOLT, TAP 3/8-16 X 1-1/2 (FULL THD)                                   | 2    |  |
| 27  | 10312          | WASHER, FLAT 1/2 SAE ZINC   | 2    |  |
| 28  | 10025          | WASHER, FLAT 3/8 SAE ZINC   | 12   |  |
| 29  | 10811          | WASHER, LOCK 3/8 ZINC   | 6    |  |
| 30  | 10404          | NUT, HEX 3/8-16 ZINC  | 6    |  |




### **ILLUSTRATION 7: THREE PHASE MOTOR GROUPING**



| PART  | S LISTING - IL                                     | LUSTRATION 7: THREE PHASE MOTOR GROUP   | ING                        |
|-------|--|---|----------------------------|
| ITEM# | PART#  | DESCRIPTION   | QTY.                       |
| 1     | 81022  | MOTOR, BALDOR 5HP-3PH-60HZ-230/460V   | 1                          |
| 2     | 10740  | CONDUIT LOCK NUT 3/4 NP (INSIDE JUNCTION BOX)   | 1                          |
| 3     | 16539  | STRAIN RELIEF 90D X 3/4NPT .50625   | 1                          |
| 4     | 86023  | WIRE HARNESS 12/4 X 42"LOA  | 1                          |
| 5     | 86022  | WIRE HARNESS 12/4 X 26"LOA  | 1                          |
| 6     | 41053  | STRAIN RELIEF 1/2NPT X .625750"   | 2                          |
| 7     | 10982  | TIE, CABLE, BLACK NYLON 11-1/4"   | 2                          |
| 8     | 16405<br>16406                                     | STARTER ACI #128841 START-STOP 200/240V COIL 11.3-16A<br>STARTER ACI 440/480V COIL 5.5-7.5A O/L<br>REPLACEMENT PARTS:   | 1<br>1                     |
|       | 16617<br>16618<br>16622<br>16623<br>16632<br>16635 | STARTER CONT./COIL ACI SK18.310-230 STARTER CONT./COIL ACI SK18.310-460 STARTER AC COIL 200/240V-60HZ STARTER AC COIL 440/480V-60HZ STARTER OVERLOAD RELAY 5.5-7.5 AMP STARTER OVERLOAD RELAY 11.3-16.0 AMP | 1<br>1<br>1<br>1<br>1<br>1 |
| 9     | 86027  | MOUNTING BRKT., STARTER (ACI)   | 1                          |
| 10    | 11732<br>10384                                     | SCREW, MACHINE 10-32 X 1-3/4 RHP (INSIDE STARTER)<br>SCREW, MACHINE 10-32 X 1 RHP (INSIDE STARTER)  | 2<br>1                     |
| 11    | 10832  | NUT, KEPS LOCK 10-32 ZINC   | 2                          |
| 12    | 10846  | SCREW, CAP STSHW 1/4-20 X 1/2   | 2                          |
| 13    | 10038  | WASHER, LOCK 1/4 ZINC   | 2                          |
| 14    | 11565  | CLAMP, LOOM, 5/8" (SAE SIZE 10)   | 1                          |
| 15    | 10831  | WASHER, LOCK, INT. TOOTH #10  | 1                          |
| 16    | 10877  | SCREW, CAP STSHW 10-24 X 1/2  | 1                          |
| 17    | 15204  | PLUG, RECT. HOLE, PLASTIC SNAP-IN   | 1                          |
| 18    |  | KEY 1/4"SQ (INCLUDED WITH MOTOR)  | 1                          |
| 19    | 81006  | SHEAVE 3"OD X 3GR.A X 1-1/8"BORE  | 1                          |
| 20    | 81007  | BELT AX-33 (1/2" X 35"OL)   | 3                          |
| 21    | 81010  | MOUNT BRKT., CHANNEL, SB-14   | 2                          |
| 22    | 10205  | NUT, HEX LOCK 1/2-20 ZINC (USED AS SPACER)  | 2                          |
| 23    | 10802  | BOLT, CARRIAGE 3/8-16 X 1 ZINC  | 2                          |
| 24    | 10804  | BOLT, CARRIAGE 3/8-16 X 1-1/2 F.T.  | 2                          |
| 25    | 10480  | BOLT, TAP 3/8-16 X 1-1/2 (FULL THD)   | 2                          |
| 26    | 10312  | WASHER, FLAT 1/2 SAE ZINC   | 2                          |
| 27    | 10025  | WASHER, FLAT 3/8 SAE ZINC   | 12                         |
| 28    | 10811  | WASHER, LOCK 3/8 ZINC   | 6                          |
| 29    | 10404  | NUT, HEX 3/8-16 ZINC  | 6                          |




### **ILLUSTRATION 8: AIR MOTOR GROUPING**



|      | PARTS LISTING - ILLUSTRATION 8: AIR MOTOR GROUPING |                                       |      |      |        |  |         |
|------|--|---------------------------------------|------|------|--------|--|---------|
| ITEM | PART#  | DESCRIPTION                           | QTY. | ITEM | PART#  | DESCRIPTION                                      | QTY.    |
| 1    | 80050  | MOTOR, GAST AIR 5 HP                  | 1    | 26   | 80063  | HOSE, PUSH-ON 1/2"ID X 6-1/2"L                   | 1       |
|      |  | 8AM-FRV-2B                            |      | 27   | 10711  | VALVE, BALL 1/2 FPT                              | 1       |
| 2    | 80065  | MOUNT, AIR MOTOR, ASB-14              | 1    | 28   | 10724  | ELBOW, STREET 1/2NPT X 90                        | 1       |
| 3    | 10606  | SCREW, CAP 5/16-18 X 1-1/4            | 4    | 29   | 10790  | CONDUIT LOCK NUT 1/2 NP                          | 2       |
| 4    | 10213  | WASHER, FLAT 5/16 SAE ZINC            | 4    | 30   | 80071  | LUBRICATOR, 1/2 NPT                              | 1       |
| 5    | 10801  | WASHER, LOCK 5/16 ZINC                | 4    |      |        | SMC AL40-N04-Z                                   |         |
| 6    | 10054  | NUT, HEX 5/16-18 ZINC                 | 4    | 31   | 80072  | BRACKET, T-TYPE, SMC Y40T                        | 1 1     |
| 7    | 10340  | BOLT, TAP 1/2-13 X 3<br>(FULL THREAD) | 2    | 32   | 80070  | (INCLUDES 2 O-RINGS)<br>FILTER/REG., 1/2NPT      | 1       |
| 8    | 10417  | NUT, HEX 1/2-13 ZINC                  | 2    |      |        | SMC AW40-N04H-Z                                  |         |
| 9    | 80066  | BRACKET, MOTOR MOUNT                  | 1    | 33   | C90207 | GAUGE, AIR PRESSURE,<br>SIDE STEM                | 1       |
| 10   | 10309  | SCREW, CAP 3/8-24 X 1-1/4             | 3    |      | 00070  | <u> </u>   | $\perp$ |
| 11   | 10025  | WASHER, FLAT 3/8 SAE ZINC             | 3    | 34   | 80073  | BRACKET, PIPING ADAPTOR,<br>T-TYPE, SMC E40T-N04 | 1       |
| 12   | 10811  | WASHER, LOCK 3/8 ZINC                 | 3    |      |        | (INCLUDES O-RING)                                |         |
| 13   | 10014  | NUT, HEX 3/8-24 ZINC                  | 3    | 35   | 80075  | COUPLER, AIR HOSE, 1/2 MPT                       | 1       |
| 14   | 10914  | SCREW, CAP 1/2-13 X 1                 | 2    | 36   | 63040  | CABLE, WHIPCHEK SAFETY                           | 1       |
| 15   | 10312  | WASHER, FLAT 1/2 SAE ZINC             | 2    |      |        | 1/8 X 20-1/4                                     |         |
| 16   |  | KEY 3/16 X 1                          | 1    | 37   | 80074  | BRACKET, F.R.L. MOUNTING                         | 1       |
|      |  | (INCLUDED W/ MOTOR)                   |      | 38   | 10819  | BOLT, CARRIAGE 5/16-18 X 1                       | 4       |
| 17   | 80016  | SHEAVE 3"OD X 2GR.B X 3/4B            | 2    | 39   | 10213  | WASHER, FLAT 5/16 SAE ZINC                       | 4       |
| 18   | 10251  | BELT B-34 (21/32" x 37"OL)            | 2    | 40   | 10801  | WASHER, LOCK 5/16 ZINC                           | 4       |
| 19   | 10728  | PIPE NIPPLE, CLOSE 1/2NPT             | 4    | 41   | 10054  | NUT, HEX 5/16-18 ZINC                            | 4       |
| 20   | 80060  | PIPE UNION 1/2 NPT (GALV.)            | 2    | 42   | 10018  | SCREW, CAP 1/4-20 X 3/4                          | 4       |
| 21   | 80057  | BUSHING, HEX 1 X 1/2 NPT              | 3    | 43   | 10602  | WASHER, FLAT 1/4 SAE ZINC                        | 8       |
| 22   | 80056  | (GALV.)<br>  PIPE TEE, FEMALE 1"NPT   | 1    | 44   | 10038  | WASHER, LOCK 1/4 ZINC                            | 4       |
| 22   | 00000  | (GALV.)                               | '    | 45   | 10013  | NUT, HEX 1/4-20 ZINC                             | 4       |
| 23   | 80055  | MUFFLER, AIR MOTOR,<br>1/2NPT MALE    | 2    | 46   | 80077  | MOUNTING BRKT., FRL<br>LEFT SIDE                 | 1       |
| 24   | 10734  | ELBOW, STREET 1/2NPT X 45             | 1    | 47   | 80076  | MOUNTING BRKT., FRL<br>RIGHT SIDE                | 1       |
| 25   | 80061  | BARB, PUSH-ON<br>1/2HOSE X 1/2MPT     | 2    | 48   | 15204  | PLUG, RECT. HOLE,<br>PLASTIC SNAP-IN             | 1       |




### WIRING DIAGRAM FOR ROTARY SWITCH






### WIRING DIAGRAM FOR STARTER

### 60HZ 3-PHASE 230/460V






### WIRING DIAGRAM FOR 1 PHASE 60Hz MOTOR BALDOR CAT. NO. L3608TM






### WIRING DIAGRAM FOR 3 PHASE 60Hz MOTOR BALDOR CAT. NO. EM3613T



### WIRING DIAGRAM FOR HONDA ENGINE





# PARTS FINDERS Search Website Can't Find







Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

### Need parts?

Click on this link: <a href="http://www.discount-equipment.com/category/5443-parts/">http://www.discount-equipment.com/category/5443-parts/</a> and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto, Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S. Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar