



Mandatory Bulletin No. CO20070807 Subject: Unbalanced Impeller Model: QP4TZ Product Group: Trash Pumps Date: 08/07/2007

SERVICE BULLETIN

Group: CO

THIS SERVICE BULLETIN IS MANDATORY!

Series/Parts Affected:

Machines Affected: QP-4TZ S/N 4TZ-0003~4TZ-0052

SERVICE INFORMATION

Problem:

• Unbalanced impeller due to wrong components being installed on pump.

Remedy:

• Replace incorrect impeller components with impeller P/N KIT4TZIMP (Impeller Kit).

PARTS INFORMATION				
Item	Quantity	Part #	Description	Remarks
1		KIT4TZIMP	KIT, IMPELLER	INCLUDES ITEMS 2 THRU 6
2	1		IMPELLER	
3	1		KEY, SHAFT	IMPELLER
4	1		WASHER, LOCK	IMPELLER
5	1		BOLT	IMPELLER
6	1		WASHER, FLAT	IMPELLER

INSTALLATION INSTRUCTIONS

WORK SAFFI Y!

Only a *qualified service technician* with proper training should perform this r your parts installation.

Required Tools/Materials

- 3/8 Ratchet with 14 mm drive socket
- Rubber Mallet •
- Chemsearch[™] (Rust Lubricant)

Please make sure all parts are accounted for.

Safety Procedures

Perform the following before attempting installation:

- 1. Place the pump on level secure ground that is free of dirt and debris.
- 2. Wear safety glasses, steel toed boots and any other safety protection that might be required for the modification.

Impeller Replacement (Reference Figure 1)

- 1. Remove drain cover from pump casing by turning the locking knobs (Figure A) counterclockwise to loosen. Once the locking knobs have been loosened and folded back, pull the drain cover forward until it clears the pump casing. Set drain cover aside in a safe place.
- 2. Using a 3/8 ratchet with a 14 mm socket (Figure B), remove the impeller bolt from the engine shaft. Discard the impeller bolt it will not be used again.
- 3. Attached to the impeller bolt (Figure C) are the incorrect impeller washers. *Discard all* washers; they will not be used again.
- 4. Using a can of ChemsearchTM (Figure **D**) or equivalent, a moly-lubricant, spray the area around the shaft key. Tap the impeller with a rubber mallet to dislodge it from the engine shaft. Remove the impeller and shaft key. Discard the impeller and shaft key. They will not be used again.
- 5. Install the new impeller and shaft key onto the engine shaft as shown in Figure E.
- 6. Using the new impeller bolt, place the new impeller lock washer onto the bolt as shown in Figure F. Next, place the impeller washer with the key side (raised notch) facing outward onto the impeller bolt.
- 7. Insert impeller bolt along with associated hardware (Step G) into engine shaft. Be sure to align the notch on the impeller washer with the key-way on the engine shaft. This will lock the impeller washer in place. Tighten impeller bolt to 22 FT-LBS.
- 8. Reinstall drain cover (Figure H) back onto pump casing. Turn locking knobs clockwise to secure drain cover.




Figure 1. Impeller Replacement

Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari ganity apulartari. Na sali Ina Badu mu Parla na Asaratari ke tarata da da Katani Alaki Ying Katani katalari Ina da mu Parla na Parla Asaratari ke tarata da da taratari ya Katani kata Katani katalari	SCOL Brand	
When Source Mades The DifferenceIII Sections	* Vold	A(8.5.5
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
An Andrew Territory Territory Territory Territory Territory Territory	Bit: Brailforte	Api pra con ·
State Second and Areas	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description fam You Are Locking For	CdPlac
		N 2
	21/14	Ermi *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar