



If there is a hole pinched in your oil leveler sack you may notice the following:

- 1. Hydraulic oil leaking from the oil leveler sack bolt (front of rebar cutter).
- 2. The cutter rod will not move.

TOOLS REQUIRED

- 3/8" Drive Ratchet
- 6 mm Allen Socket
- 8 mm Allen Socket
 17 mm Combination End Wrench

Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari ganity apulartari. Na sali Ina Badu mu Parla na Asaratari ke tarata da da Katani Alak Ying Katala da	SCOL Brand	
When Source Mades The DifferenceIII Sectors	* Vold	Alberts
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
a Print Street S	Bit: Brailforte	Api pra con ·
State Second and Area	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description from Yes Are Locking For	CdPlac
		De
	21/14	Evel *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar

INSTALLATION INSTRUCTIONS

 Remove the hydraulic oil drain plug with a 17 mm combination end wrench. Drain the oil into an oil pan.

 Once the hydraulic oil has been removed, use a 6 mm Allen socket screw and 3/8" ratchet to remove the 14 bolts that hold the bar holder in place.





CAUTION: Make sure to leave the two bottom bolts and one top bolt for last. Slowly and evenly back the bolts off. This will relieve the tension on the cutter rod return spring.

3) Once the rod holder is removed from the rest of the unit, inspect the spring and see if the ending edge rests
directly above the oil leveler sack. If so, you may find the oil leveler sack with a hole in it as shown on the right.





- If a hole is found in the oil leveler sack, replace it with a new one (part number H9T43899N1).
- 5) To replace the oil leveler sack, remove the allen head bolt found in front of the bar holder using an 8 mm allen socket screw and ratchet. Remove the oil leveler sack from the bar holder.

6) Installing the new oil leveler sack is the opposite of its removal. Torque the oil leveler sack bolt to 15 foot lbs.

7) After installing the new oil leveler sack, place the cutter rod return spring so that the ending edge rests off to the side of the unit.







Service Bulletin RC20050713

8) Place the bar holder over the cutter rod. Make sure that when placing the two together you do not pinch or catch any part of the sack.

9) Once aligned correctly, press down on the bar holder end and start replacing the 14 bolts. Start with 3 to 4 bolts to hold the two ends together and then replace the remaining bolts. Retorgue the bolts to 25 foot lbs.

10)Replace the hydraulic oil with 10.2 oz of Shell Tellus oil # 32 or Exxon Teresstic #32.

Replacing oil:

- a) Turn the cutter so oil fill port is on top side. Fill with oil unit it overflows. Shake the cutter up and down to release any air bubbles that may be present and over fill again. Replace bolt in fill port and wipe off any excess oil.
- b) Note: This step is also for checking oil level and adding make-up oil. Plug cutter in and place a 1/4 rebar in bar holder. Turn on switch to activate the cutter rod and allow the blade to touch the rod, and then release the switch. Turn cutter so that oil fill port is on the top side, remove the oil fill plug and repeat oil fill procedure (step a). When finished, continue the cutting process started earlier.





Search Website by Part Number Discount	Search Manual Library For Parts Manual & Lookup Part Numbers – Purchase or Request Quote	Can't Find Part or Manual? Request Help by Manufacturer, Model & Description
Equipment		Parts Order Form
		1 Nouline faile
	Search Manuals	22mgb
	Histope scale performant and period speptimetic party and some manuality in scale, per parts	NOC.
	theat	
ni Zapitrami i siya Yoni na kasarata ke tarata di katalari ganity apulartari. Na sali Ina Badu mu Parla na Asaratari ke tarata da da Katani Alak Ying Katala da	SCOL Brand	
When Source Mades The DifferenceIII Sectors	* Vold	Alberts
Printe universe interest for any posterior in the second s		Oh.
200 2004 tol tourideta for Tableta for	Sond	DateTopics
a Print Street S	Bit: Brailforte	Api pra con ·
State Second and Areas	Packharden. Ester Part Norder/Set repared/	24:36
Char State on A and Minash Minash and Minash State of Minash		A = x*
	Examples Enter Description from Yes Are Locking For	CdPlac
		De
	21/14	Evel *

Discount-Equipment.com is your online resource for quality parts & equipment.

Florida: 561-964-4949 Outside Florida TOLL FREE: 877-690-3101

Need parts?

Click on this link: http://www.discount-equipment.com/category/5443-parts/ and choose one of the options to help get the right parts and equipment you are looking for. Please have the machine model and serial number available in order to help us get you the correct parts. If you don't find the part on the website or on one of the online manuals, please fill out the request form and one of our experienced staff members will get back to you with a quote for the right part that your machine needs.

We sell worldwide for the brands: Genie, Terex, JLG, MultiQuip, Mikasa, Essick, Whiteman, Mayco, Toro Stone, Diamond Products, Generac Magnum, Airman, Haulotte, Barreto,
Power Blanket, Nifty Lift, Atlas Copco, Chicago Pneumatic, Allmand, Miller Curber, Skyjack, Lull, Skytrak, Tsurumi, Husquvarna Target, Stow, Wacker, Sakai, Mi-T-M, Sullair, Basic, Dynapac, MBW, Weber, Bartell, Bennar Newman, Haulotte, Ditch Runner, Menegotti, Morrison, Contec, Buddy, Crown, Edco, Wyco, Bomag, Laymor, EZ Trench, Bil-Jax, F.S.
Curtis, Gehl Pavers, Heli, Honda, ICS/PowerGrit, IHI, Partner, Imer, Clipper, MMD, Koshin, Rice, CH&E, General Equipment, Amida, Coleman, NAC, Gradall, Square Shooter, Kent, Stanley, Tamco, Toku, Hatz, Kohler, Robin, Wisconsin, Northrock, Oztec, Toker TK, Rol-Air, APT, Wylie, Ingersoll Rand / Doosan, Innovatech, Con X, Ammann, Mecalac, Makinex, Smith Surface Prep,Small Line, Wanco, Yanmar