

## PISTON CUP ASSEMBLY MODIFICATION

The new piston cup assembly now features a slightly tighter tolerance and extend cup life.

**Effective Machine Serial # H090088 (September 2017)**

**New Cup Identification: Color Yellow**



**(New)**  
Face Plate  
Part # 806441TT



**(New)**  
Piston Cup  
Part # EM98050Y



**(New)**  
Bronze Ring  
Part # EM806440



**(New)**  
Felt Holder  
Part # EM806439



**(New)**  
Piston Head Adaptor  
Part # EM806438